LOCATION: 100-B(2)-\*

HYDRAULIC CONDITIONS: Inconclusive

PERTINENT OBSERVATIONS: Extremely low water production

Drilled 100-B(2)-\* to a total depth of 401. No indication of water production observed in drilling fluid discharge while drilling to **T.D.** no water detected in borehole with water probe at T.D. after overnight recovery. The aquifer is fractured Orejon Andesite, but fracture **porosity** in this area does not appear very effective. Water level rose 28' in 18 days (see Well Summary sheet for details).